Linear Height SERIES 518 — High-performance 2D Measurement System

- This is a precision height gage featuring high accuracy and outstanding ease of use. It is useful not only in height measurement but also in a wide range of applications such as inspection of moulds and precision parts.
 Easy operation using keypad and touch
- screen navigation allows intuitive operation that is suitable even for beginners.
- The built-in scale is dirt-resistant and can be reliably used on shop floors.
- Various interfaces are available, including connection to a printer, a PC, and our wired or wireless communication system.
- Pneumatic full/semi-floating suspension system allows adjustment of air-cushion height.
- It is easily expandable to support various types of optional probes to meet your different measurement needs.



SPECIFICATIONS

Model			LH-600F	LH-600FG	
Code No.		mm	518-360-11	518-361-11	
Code No.		inch/mm	518-360-13	518-361-13	
Power grip			Without power grip	With power grip	
Measuring range (Stroke)		Stroke)	0 to 977 mm (600 mm) 0 to 38 in (24 in)		
Resolution			0.0001/0.001/0.01/0.1 mm (selectable) 0.000001/0.00001/0.0001/0.001 in (selectable)		
	Indicati	on accuracy*1	± (1.1 + 0.6L/600) μm, L= Arb	pitrary measuring height (mm)	
	Repeata	ability*1	Plane: 0.4 μm (2 σ),	. Hole: 0.9 μm (2 σ)	
Accuracy	Perpendicularity (forward and backward)* ²		5 μ	ım	
	Straightness (forward and backward)* ²		4 µm		
Driving me	thod (sp	eed)	Motor-driven (5, 10, 15, 20, 25, 30, 40 mm/s: 7 steps)/Manual		
Scale unit			Photoelectric incrermental encoder STVC-20Z		
Measuring	force		1 N (automatic constant-force function)		
Main unit i	moving I	mode	Full-floating (moving)/Semi-floating (measuring) Air bearing (built-in compressor)		
Display uni	t		8.4 inch touch-screen, LCD		
Adjustmen	t of disp	lay unit	Stepless tilt adjustment: 0 to 40° Stepless swivel adustment: -30 to 180°		
Preventive	mainten	ance	Scale status notification, calibration schedule notification		
Probe diam	neter cor	npensation	Semi-automatic compensation using the probe diameter calibration block (standard accessory) Compensation by inputting the probe diameter		
Power sou	rce		AC adapter 100-240 V±10% 50/60 Hz/Battery (NiMH)		
Battery ope	eration t	ime* ³	Battery powered (standard): 4 hours*4, Powered by 2 batteries: 8 hours		
Battery cha	arging tir	me*5	Approx. 3.5 hours (can	be used while charging)	
Dimension	s (W×D×	(H)	238×492	×996 mm	
Mass			26.1 kg	26.6 kg	
Operating '	tempera	ture/humidity ranges	5 to 40 °C/20 to 80%	RH (non-condensing)	
Data outpu	ut		Digimatic D1/D2/S1 (bi-d	irectional communication)	

• Use in an environment that is as close as possible to 20 °C, and subject to minimal temperature change over time.

*1: Indication accuracy and repeatability represent the values obtained when the standard ø5 stepped prove is used.

*2: Guaranteed when using the Lever Head (519-521) and Mu-Checker (519-561).

*3: 25% operation of vertical movement by suspension and motor

*4: One battery pack (**12AAF712**) is provided as standard.

*5: When ambient temperature is 30 °C or higher, the battery may not charge sufficiently.

LH Communication-Tool V1.0 software for creating inspection reports and configuring system settings

You can easily create and save inspection reports and configure device parameters.

- * Available at Mitutoyo website for free
- download.
- * To connect to a PC, use a USB cable (type A-B).



	a municipality of the		1.B.down	
	Mikutoyo		and the second se	HOUSE
	Tota Literation tand temperat			
				-
	Liti settings			
	C Tantala to pr		18.04 Hold	100 M
		Date		
	ET seatting inc.	Data format	-	
		diverse in the second s		
	20 MAR 1 M	1		10
	Anton office . Toward Ming			
	- Benka Suttings	E-MAN .		
and the second se	144	Companyor, display of allochus	405	1 808 0 8 10
ALL	- Landa	10 C		a man 10 10 10
and a second	- Manage London		·	
	- Nameron and American Visibility Taxa	Passed	444	
	 Tempenhow Environment Oerditions 			And a 1 100 10 10 10
	 Automatic measurement (for programment) 	The sale	1 111	1 844 - 1 10
	- Romor of Sigh ; Units			A 140 14 14
	Contraction		·	. · · · · · · · · · ·
	- Common adding			a 100 14 8 14
	formation and the	LOCACIA		
	diamate .			
	- utilinary	A		
	- Palitiens	Territorial and		
) Celebration	10 ¹		



Adjustable to easy-to-see angle



Measurement guidance



Intuitive operation thanks to guidance



Home screen

Measurement menu display is easy to understand visually. The guidance makes it easy for first-time users to operate the system.



2D measurement - Pre-placement -This function allows the user to register the hole position of the workpiece before measurement.

Perpendici	Perpendicularity d			- 📼 2021/07/07
				72.6720 mm
_d Pero	endicularity		-0-	0.2798 mm
NT 🖬	0.0233	mm	100	Z1
A A	90.0076	deg	75	
🖹 F	0.0193	mm	50	
Z	60.0000	mm	25	
			-0.05	0 0.05
				×

Perpendicular/straightness measurement - Graph creation -You can check the measurement results of perpendicularity and straightness in real time during measurement.

1	TEST-PRG1	Note		
2	TEST-PRG2	1D		
3	TEST-PRG3	A 1 1	CIRCLE-001	67.00
4	-	2 1	CIRCLE-002	25.00
5	-	1		
6	-			
7	-	V		E

Part program measurement

You can easily create, execute, edit, and even display the results of part programs.



05

Optional products for outputting measurement data

Code No.	Product name
12AAY481	Receipt printer (for Japan)*1
12AAY482	Receipt printer (for North America)*1
12AAY483	Receipt printer (for EU countries, excluding the UK)* ¹
12AAY484	Receipt printer (for the UK)*1
12AAN052	Printer paper for receipt printer (set of 10)
12AAY485	Printer mounting attachment
12AAN146	Connection cable for printer
-	(USB memory device)* ²
12BAF812	USB cable (type A - type B) (2 m)
543-700B	Digimatic indicator (ID-C0512NXB)
543-701B	Digimatic indicator (ID-C0512MNXB)
519-521	Lever head probe MLH-521
519-561	Mu-checker M-561
936937	Digimatic cable (1 m)
965014	Digimatic cable (2 m)
264-505	Digimatic mini processor (DP-1VA)
264-020	Input tool (IT-020U)
06AGQ001F	Input tool (USB-ITN-SF)
06AGL011	Bidirectional digimatic S1 cable, Flat and straight (1 m)
06AGL021	Bidirectional digimatic S1 cable, Flat and straight (2 m)
12AAJ088	Foot switch
02AZD810D	U-WAVE-R
02AZD730G	U-WAVE-T (IP67 type)
02AZD880G	U-WAVE-T (Buzzer type)
12AAY486	U-WAVE T mounting bracket
02AZG011	Bidirectional Digimatic S1 cable for U-WAVE-T (160 mm)
264-626	U-WAVE-TMB (IP67 type)
264-627	U-WAVE-TMB (Buzzer type)

*1 A small printer (optionally battery-powered) that can be mounted on the main unit. It includes a printer cable and mounting bracket.

*2 USB memory devices should be formatted with FAT16/32. NTFS and exFAT are not supported.

DIMENSIONS



Optional Accessories



No.	Code No.	Item
(1)	12AAY602	Depth stylus 70 ø2 ball
(2)	12AAY603	Depth stylus 150 ø2 ball
(3)	12AAY604	Depth stylus 300 ø2 ball
(4)	12AAY605	Depth stylus 70 ø4 ball
(5)	12AAY606	Depth stylus 150 ø4 ball
(6)	12AAY607	Depth stylus 300 ø4 ball
(7)	12AAY599	Depth stylus 70
(8)	12AAY600	Depth stylus 150
(9)	12AAY601	Depth stylus 300
(10)	12AAY343	ø5 stepped probe (standard accessory)
(11)	12AAA792	Dial indicator holder (mm type)*1
(11)	12AAA837	Dial indicator holder (inch type)*1
(12)	12AAA793	Probe extension holder
(13)	12AAB136	ø10 mm cylindrical probe
(14)	12AAY595	Extension holder 100
(15)	12AAY596	Extension holder 200
(16)	12AAC073	Tapered probe (ø20)
(17)	12AAC072	Depth probe
(18)	12AAF666	ø1 mm ball probe (coaxial type)
(19)	957261	ø2 mm ball probe (coaxial type)

No.	Code No.	Item		
(20)	12AAF667	ø2 mm ball probe (coaxial type) Ruby ball		
(21)	957262	ø3 mm ball probe (coaxial type)		
(22)	957263	ø4 mm ball probe (coaxial type)		
(23)	12AAB552	ø10 mm ball probe (coaxial type)		
(24)	12AAF668	ø10 mm ball probe (coaxial type) L: 82 mm		
(25)	12AAF669	ø10 mm ball probe (coaxial type) L: 120 mm		
(26)	12AAF670	ø5 mm disk probe		
(27)	12AAF671	ø10 mm disk probe		
(28)	957264	ø14 mm disk probe		
(29)	957265	ø20 mm disk probe		
(30)	12AAY598	ø25 disk stylus		
(31)	12AAF672	ø1 mm ball offset probe		
(32)	12AAF673	ø2 ball stylus (eccentric type)		
(33)	12AAA788	ø4 mm ball offset probe		
(34)	12AAA789	ø6 mm ball offset probe		
(35)	226118	M3 CMM stylus adapter* ²		
(36)	226117	M2 CMM stylus adapter* ²		
(37)	05HAA394	ø5 ball stylus* ³		
(38)	12AAY597	ø5 ball stylus L130		
	12AAF712	Additional battery pack		

*1 A dial indicator is not included.
 *2 For enabling CMM stylus to be used.
 *3 The stylus is attached to ø5 stepped probe (**12AAY343**) and provided as standard.
 Note 1: A gauge block may be required for zero-setting depending on the probe and contact point.
 Note 2: Refer to the **E12012** catalog for more details.



QM-Height SERIES 518 — High-performance Height Gage

- This highly precise height gage is useful not only in height measurements but also in a wide range of applications such as measurement of steps, inside and outside diameters, and runouts.
- Easy-to-view, simple control panel enables most measurements to be made with a single keystroke.
- SPC (Digimatic) and RS-232C data output allow easy data management with a PC.
- Pneumatic floating models, which feature an air-suspension mechanism, can move smoothly on a surface plate (accuracy cannot be guaranteed for measurement while the unit is air-suspended).
- It features a long continuous operating time of approximately 1,200 hours with four AA alkaline batteries. (Four commercially available NiMH/HR6 rechargeable batteries can also be used.)



SPECIFICATIONS

Codo No	Metric	518-240	518-242	518-244	518-246	
Coue No.	Inch/Metric	518-241	518-243	518-245	518-247	
Moscuring r	ango (stroko)	0 to 465 mm	0 to 715 mm	0 to 465 mm	0 to 715 mm	
Measuring range (stroke)		(350 mm/14 in)	(600 mm/24 in)	(350 mm/14 in)	(600 mm/24 in)	
Metric		0.001 mm/0.005 mm (Selectable)				
Resolution	Inch/Metric	0.001/0.005 mm 0.00005/0.0001/0.0002 in (Selectable)				
A	Indication accuracy*1		± (2.4 + 2.1	1L/600) µm		
Accuracy	Repeatability*1		2 <i>0</i> ≤	1.8 µm		
Perpendicula	irity*2	7 µm	12 µm	7 μm	12 µm	
Guiding met	hod		Roller k	bearing		
Drive metho	d		Manual	(wheel)		
Measuremen	nt principle	Electromagnetic induction absolute encoder				
Measuring for	orce	1.5±0.5 N				
Data output	ports	Digimatic/USB* ³				
Air-floating system		Not included Included (for positioning only)*4			sitioning only)*4	
Power source		Alkaline AA /LR6 batteries×4 (standard accessories)/AC adapter (optional accessory)*5/ Supports NiMH (HR6) rechargeable batteries×4				
Datton life a	uidelines*fi	Approx. 1,200 hours (without using the air-floating system)				
battery me g	uluelines	Approx. 90 hours (when using the air-floating system)				
Mass		25 kg	29 kg	26 kg	30 kg	
Dimensions (W×D×H)		Stroke 350 mm type: 280×273×784 mm Stroke 600 mm type: 280×273×1016 mm				
Operating temperature (recommended)		0 to 40 °C (10 to 30 °C)				
Operating humidity		20 to 80% RH (non-condensing)				
Storage tem	perature		-10 to	50 °C		
Storage hum	nidity		5 to 90% RH (n	on-condensing)		

 Standard Accessories: 05HZA148 ø5 mm stepped probe, 12AAA715 Probe diameter calibration block, Alkaline batteries×4 (AA/LR6) (For operational checks)

*1 Indication accuracy and repeatability represent the values obtained when the standard ø5 stepped probe is used. It should be used in an environment as close to 20 °C as possible, with minimal temperature changes. In the case of diameter, minimum (maximum) value, circle pitch or difference measurement, measuring errors may be larger than the accuracy ratings listed in the table due to variations in measuring force during a scanning measurement, which differs from height measurement. *2 Indicates the value obtained from the measurement of a straight surface placed perpendicular to the the base reference

*2 Indicates the value obtained from the measurement of a straign surface piece perpendicular to the the base reference surface using the Lever Head (519-521) and Mu-checker (519-551).
 *3 Requires special communication driver. Consult your local Mitutoyo Sales Office for details. These can be downloaded from the Mitutoyo web site. https://www.mitutoyo.co.jp/eng/contact/products/usb/index.html
 *4 When using a model with the air-floating system, it is advisable to use a JIS 1 class, or higher, surface plate. Using on surfaces with scratches or unevenness may prevent the system operating to the specified performance.
 *5 The AC datase cancer the used to schere or personable batteries.

*5 The AC adapter cannot be used to recharge rechargeable batteries.

*6 Battery life depends on the operating conditions. In particular, it is more economical to use the optional AC adapter to power the instrument if the application requires prolonged use of the air-floating system.

Measurement example

MeasurLink® ENABLED

• Height measurement









Runout measurement







05

Height Gages

DIMENSIONS



Optional Accessories



Optional accessories that enable centralized data management

Code No. Item name					
Small printer e	Small printer equipped with Data Logger				
264-505 DP-1VA LOGGER					
936937 Digimatic connection cable (1 m)					
965014 Digimatic connection cable (2 m)					
06AFZ050 USB cable (A-microB)					
Measurement Data Input Unit					
06AFM380D USB Input Tool Direct USB-ITN-D					
Measurement of	Measurement data wireless communication system				
02AZD730G U-WAVE-T (Transmission unit) (IP67 type)					
02AZD880G	U-WAVE-T (Transmission unit) (Buzzer type)				
02AZD790D	U-WAVE-T dedicated cable (Standard use)				
02AZE140D	U-WAVE-T dedicated cable (For foot switch)				
02AZD810D	U-WAVE-R				
02AZE990	U-WAVE mounting bracket				
Measurement of for Excel USB-	Measurement data collection software for Excel USB-IT PAK V2.1/V3.0				
Measurement (Measurement data network system Measurlink®				

Contact points for a wide range of measurements

Item	Code No.	Description	
	Depth probe		
(1)	12AAC072	Depth probe	
	Special holder		
(2)	12AAA792	Holder for dial indicator	
(3)	12AAA793	Holder (Long)	
	Interchangeable	contact points for ø5 mm stepped probe	
(4)	957265	ø20 mm disk	
(5)	957264	ø14 mm disk	
(6)	957261	ø2 mm ball (coaxial type)	
(7)	957262	ø3 mm ball (coaxial type)	
(8)	957263	ø4 mm ball (coaxial type)	
(9)	12AAA789	ø6 mm ball (eccentric type)	
(10)	12AAA788	ø4 mm ball (eccentric type)	
	AC Adapter		
	06AGZ369JA	AD620JA for Japan/U.S.	
	06AGZ369D	AD620D for the EU	
	06AGZ369E	AD620E for the UK	
	06AGZ369K	AD620K for Korea	
	06AGZ369DC	AD620DC for China	
	Other		
	05HZA173	Scriber*	

* Used for measurements, cannot be used for scribing. Note: A gauge block may be required for zero-setting depending on the probe or contact point to be used.



Digimatic Height Gage SERIES 192 — Multi-function Type with SPC Data Output

- Double-column structure ensures stable measurements.
- Ergonomic base fits comfortably in the hand.
- Inclined handle improves slider ergonomics.
- Bidirectional touch-trigger probe is available as an optional accessory.
- Provided with a long scriber (150 mm).



ò

05





SPECIFICATIONS

Metric	_	
Code No.	Range (mm)	R

Code No.	Range (mm)	Resolution (mm)	Maximum permissible error Empe (mm)*	Response speed (mm/s)	Height (mm)	Mass (kg)
192-663-10	0 - 300	0.01/0.005	±0.02	Approx. 500	510	5.7
192-664-10	0 - 600	(selectable)	±0.04		802	8.3
192-665-10	0 - 1000	(selectable)	±0.06		1228	15.7

Inch / Metric	i.					
Code No.	Range (in)	Resolution	Maximum permissible error EMPE (in)*	Response speed (mm/s)	Height (mm)	Mass (kg)
192-670-10	0 - 12	0.01 mm/0.005 mm	±0.001		510	5.7
192-671-10	0 - 18	(selectable)	±0.0015	Approx E00	649	7.5
192-672-10	0 - 24	0.0005 in/0.0002 in	±0.0015	Approx. 500	802	8.3
192-673-10	0 - 40	(selectable)	±0.0025		1228	15.7

• Power source: SR44 battery (1 pc.), 938882 included as standard (for operational checks)

Battery life: Approx. 3,500 hours in continuous use

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

DIMENSIONS

Mitutoyo



Functions (Refer to page 05-8)

Standard Accessories

Code No.	Description	Models
905200	Scriber	192-663-10 192-664-10 192-665-10
905201	Scriber	192-670-10 192-671-10 192-672-10 192-673-10
05GZA033	Scriber clamp box	192-663-10 192-664-10 192-665-10
901385	Scriber clamp box	192-670-10 192-671-10 192-672-10 192-673-10

Optional Accessories

Code No.	Туре	Description	
264-020	_	USB Input Tool Series USB Keyboard Signal Conversion Type IT-020U	
905338	F	Connection cable for IT/DP/MUX (1 m)	
905409	F	Connection cable for IT/DP/MUX (2 m)	
06AFM380F	F	USB Input Tool Direct (2 m)	
02AZD730G	IP67	U-WAVE-T	
02AZD880G	Buzzer	U-WAVE-T	
02AZE200	_	U-WAVE-T mounting bracket	
02AZD790F	F	Connection cable for U-WAVE-T (160 mm)	
02AZE140F	F	Connection cable for U-WAVE-T For foot switch	

• Bidirectional touch-trigger probe: 192-007 (mm), 192-008 (inch)

Improves accuracy in step, internal thickness, and outside width measurement by minimizing reproducibility error. A bidirectional touch-trigger probe is available as an optional accessory for **192-663-10**, **192-664-10**, **192-665-10**, **192-670-10**, **192-671-10**, **192-672-10** and **192-673-10**.



Digimatic Height Gage SERIES 192 — Multi-function Type with SPC Data Output

Functions

- Origin-setting (ABS measurement mode): Any arbitrary value can be stored as the origin point.
 Zero-setting (INC measurement mode): Displayed value can be set to zero at any arbitrary
- position of the slider.
- Origin restoration: Previously set origin is restored when switching back to ABS mode.
- Presetting (ABS INC measurement mode): Displayed value can be set to any arbitrary value,
- including negative values. Measuring direction
- Measuring direction can be switched at the press of a button. • Data hold Display value can be held. Reverts to ABS or INC mode
- when cancelled. • Alarm: Error message is displayed when overflow or overspeed
- of displayed value arises and measurement is stopped. • Data output:
- Allows integration into statistical process control and measurement systems. (Refer to page 09-3.)
- Fine and coarse height adjustment through knob and wheel combination. Slider height adjustment wheel allows fine and coarse

height adjustment. • Probe-tip diameter compensation: An adjustment is

- applied to the raw measurement data to compensate for the effect of the size of the spherical contact point used by the bidirectional touch-trigger probe.
- Presetting (2 positions): With two preset functions, two reference heights can be used relative to a surface plate.

Standard Accessories

Code No.	Description	Models
07GZA000	Scriber	192-613-10 192-614-10 192-615-10
900258	Scriber	192-630-10 192-631-10 192-632-10 192-633-10
05GZA033	Scriber clamp box	192-613-10 192-614-10 192-615-10
901385	Scriber clamp box	192-630-10 192-631-10 192-632-10 192-633-10

Optional Accessories

Code No.	Type	Description	
264-020	USB Input Tool Series USB Keyboard Signal Conversion IT-020U		
905338	F	Connection cable for IT/DP/MUX (1 m)	
905409	F	Connection cable for IT/DP/MUX (2 m)	
06AFM380F	F	USB Input Tool Direct (2 m)	
02AZD730G	IP67	U-WAVE-T	
02AZD880G	Buzzer	U-WAVE-T	
02AZE990	_	U-WAVE-T mounting bracket	
02AZD790F	F	Connection cable for U-WAVE-T (160 mm)	
02AZE140F	F	Connection cable for U-WAVE-T For foot switch	

- Double-column structure ensures stable measurements.
- Ergonomic base fits comfortably in the hand.
- Cannot be used with bidirectional touchtrigger probe.



SPECIFICATIONS

4	Metric						
	Code No.	Range (mm)	Resolution (mm)	Maximum permissible error Empe (mm)*	Response speed (mm/s)	Height (mm)	Mass (kg)
	192-613-10	0 - 300	0.01/0.005	±0.02		475	4.7
	192-614-10	0 - 600	(selectable)	±0.05	Approx. 500	802	8.3
	192-615-10	0 - 1000	(Selectable)	±0.07		1228	15.7

Inch / Metric						
Code No.	Range (in)	Resolution	Maximum permissible error Empe (in)*	Response speed (mm/s)	Height (mm)	Mass (kg)
192-630-10	0 - 12	0.01 mm/0.005 mm	±0.001		475	4.7
192-631-10	0 - 18	(selectable)	±0.002	Approx E00	649	7.5
192-632-10	0 - 24	0.0005 in/0.0002 in	±0.002	Approx. 500	802	8.3
192-633-10	0 - 40	(selectable)	±0.003		1228	15.7

Power source: SR44 battery (1 pc.), 938882 included as standard (for operational checks)
 Battery life: Approx. 3,500 hours in continuous use

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

DIMENSIONS



05

Height Gages

ABSOLUTE Digimatic Height Gage SERIES 570 — with Ergonomic Base

- New standard model which features a prismatic column and offers excellent rigidity and accuracy.
- Allows smooth elevation by the slider adjustment wheel.
- U-WAVE-T/TC/TCB (wireless data transmitter) can be installed on the back of the display unit.



Equipped with U-WAVE-T/TC/TCB

Note: When attaching the U-WAVE, use commercially available double-sided tape, etc.

SPECIFICATIONS

Metric	
wiedre	

Inch / Metric

Code No.	Range (mm)	Resolution (mm)	Maximum permissible error EMPE (mm)*	Response speed	Mass (kg)
570-402	0 - 300	0.01	±0.03	Unlimited	4.6
570-404	0 - 600	0.01	±0.05	Unimited	6.4

Maximum permissible

570-402

Digimatic Height Gage

Code No. Range Resolution Response speed Mass (kg) error Empe* 570-412 0 to 12 in/0 to 300 mm ±0.0015 in/±0.03 mm 4.6 0.0005 in/ 5.9 570-413 0 to 18 in/0 to 450 mm Unlimited 0.01 mm ±0.0020 in/±0.05 mm 0 to 24 in/0 to 600 mm 570-414 64

• Power source: SR44 battery (1 pc.), 938882 included as standard (for operational checks)

· Battery life: Approx. 5 years

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

DIMENSIONS







Functions

- Origin-setting: Any convenient reference surface, such as a surface
- plate, etc., can be stored as the ABSOLUTE origin point. ABSOLUTE measurement: After power is turned ON, measurement can be started
- without zero-setting if origin-setting was previously performed. ABSOLUTE origin position can be changed by ORIGIN button.
- Incremental measurement: Allows origin setting at any arbitrary position. In this case, the origin point is not stored after turning off the power.
- Data hold
- Display value can be held. Data output:
- Allows integration into statistical process control and measurement systems. (Refer to page 09-3.)
- Low-voltage alert:
 Low-voltage alert:
 If the battery voltage becomes low,
 Low-voltage alert:
 If the battery voltage becomes low,
 Low-voltage alert: a "B" appears in the display to alert the user before measurement is no longer possible so that the battery can be changed in good time.

Standard Accessories

Code No.	Description	Models
07ZA000	Scriber	570-402 570-404
900258	Scriber	570-412 570-413 570-414
05GZA033	Scriber clamp box	570-402 570-404
901385	Scriber clamp box	570-412 570-413 570-414

Optional Accessories

Code No.	Туре	Description	
264-020	_	USB Input Tool Series USB Keyboard Signal Conversion Type IT-020U	
905338	F	Connection cable for IT/DP/MUX (1 m)	
905409	F	Connection cable for IT/DP/MUX (2 m)	
06AFM380F	F	USB Input Tool Direct (2 m)	
02AZD730G	IP67	U-WAVE-T	
02AZD880G	Buzzer	U-WAVE-T	
02AZD790F	F	Connection cable for U-WAVE-T (160 mm)	
264-620	IP67	U-WAVE-TC	
264-621	Buzzer	U-WAVE-TC	
264-624	IP67	U-WAVE-TCB	
264-625	Buzzer	U-WAVE-TCB	
902053	_	Clamp (with dovetail groove)*	
953638	_	Holding bar*	

* For mounting test indicators, etc. (Refer to pages 07-84 and 07-85 for details.)

05

Height Gages

05

| Height Gages

Digimatic Height Gage



Functions

- Zero-setting
- +/- directional measurement
- Data hold
- Data output
- Presetting
- inch/mm reading (inch/mm models)
- Preset value memory
- Origin restoration
- Low battery voltage alert
- · Counting value composition error alert

Standard Accessories

Code No.	Description	Models
900173	Scriber	570-227 570-244
905200	Scriber	570-230 570-248
901338	Scriber clamp box	570-227 570-244
05GZA033	Scriber clamp box	570-230 570-248

Optional Accessories

Code No.	Туре	Description
264-020	_	USB Input Tool Series USB Keyboard Signal Conversion Type IT-020U
905338	F	Connection cable (1 m)
905409	F	Connection cable (2 m)
06AFM380F	F	USB Input Tool Direct (2 m)
02AZD730G	IP67	U-WAVE-T
02AZD880G	Buzzer	U-WAVE-T
02AZE200	_	U-WAVE-T mounting bracket
02AZD790F	F	Connection cable for U-WAVE-T (160 mm)
02AZE140F	F	Connection cable for U-WAVE-T For foot switch

- Simple design is easy to use.
- Scriber is provided as a standard accessory.

ABSOLUTE Digimatic Height Gage SERIES 570 — Standard Model

> • When a dial indicator or dial test indicator is used with 570-227 and 244, the dedicated holding bar (953639, overall length 50 mm) is recommended for use. However, MPE (Maximum permissible error) may be larger because the measurement point is further from the beam.



SPECIFICATIONS

Metric

Code No.	Range (mm)	Resolution (mm)	Fine feed (mm)	Maximum permissible error EMPE (mm)*	Height (mm)	Mass (kg)
570-227	0 - 200	0.01	4	±0.03	355	1.4
570-230	0 - 1000	0.01	6	±0.07	1260	16.8
Inch/Metric						

Code No.	Range (in)	Resolution	Fine feed (in)	Maximum permissible error Empe (in)*	Height (mm)	Mass (kg)
570-244	0 - 8	0.0005 in/0.01 mm-	0.16	±0.002	355	1.4
570-248	0 - 40		0.24	±0.003	1260	16.8

Power source: SR44 battery (1 pc.), 938882 included as standard (for operational checks)
 Battery life: Approx. 5,000 hours under normal use

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

DIMENSIONS





Vernier Height Gage SERIES 514, 506 — Standard Height Gage with Adjustable Main Scale

- Standard Vernier height gage. Fits comfortably in the hand and moves easily on the surface plate.
- Scriber is provided as a standard accessory.
- When installing a dial indicator or dial test indicator on **506-207**, ensure that the overall system can keep a good weight balance to ensure reliable measurement.
- The main scale slides and clamps within the column for quick and convenient zerosetting. (only for the **514** Series)

Height

(mm)

341

525

675

870

1340

±0.07

Mass

(kg)

1.4

3.1

3.4

7.4

20



SPECIFICATIONS

0 - 1000

05

Height Gages

Metric		I			
Code No.	Range (mm)	Minimum reading (mm)	Scale adjustment (mm)	Fine feed (mm)	Maximum permissibl error Empe (mm)*
506-207	0 - 200				±0.03
514-102	0 - 300			4	±0.04
514-104	0 - 450	0.02	15		10.05
514-106	0 - 600			7	±0.05

514-108 Inch / Met<u>ric</u>

Code No.	Range (in)	Minimum reading	Scale adjustment (in)	Fine feed (in)	Maximum permissible error <i>E</i> MPE (in)*	Height (mm)	Mass (kg)
506-208	0 - 8		_		±0.001	341	1.4
514-103	0 - 12			0.16		525	3.1
514-105	0 - 18	0.001 in/0.02 mm	0.6		±0.002	675	3.4
514-107	0 - 24			0.27		870	7.4
514-109	0 - 40		1	0.24	±0.003	1340	20

6

• Reading magnifier (optional): 514-102, 104, 106: 07GZA003, 514-108: 07GZA015

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

25

Standard Accessories

Code No.	Description	Models
900173	Scriber	506-207 506-208
07GZA000	Scriber	514-102 514-103 514-104 514-105 514-106 514-107
905200	Scriber	514-108 514-109
06AGR304	Scriber clamp box	506-207 506-208
05GZA033	Scriber clamp box	514-102 514-103 514-104 514-105 514-106 514-106 514-107 514-108 514-109



DIMENSIONS





any scriber position.

Dial Height Gage SERIES 192 — with Mechanical Counter

- Easy and error-free reading with both up and down digital counters as well as a dial.
 The counters and dial can be re-zeroed at
- Provided with a feed wheel for easy coarse feeding.

Standard Accessories

Description

Scriber

Scriber

Scriber

clamp box

Scriber

clamp box

Models

192-130

192-131

192-132

192-133

192-150 192-151

192-152 192-153 192-130

192-131

192-132 192-133 192-150

192-151

192-152 192-153

Code No.

07ZA000

900258

05GZA300

901385

• Carbide-tipped scriber is provided.

5 Height Gages



SPECIFICATIONS

Metric	l
inte ente	

Code No.	Range (mm)	Graduation (mm)	Maximum permissible error Empe (mm)*	Height (mm)	Mass (kg)
192-130	0 - 300		±0.03	470	4.2
192-131	0 - 450	0.01	10.0E	648	9.2
192-132	0 - 600	0.01	±0.05	798	9.8
192-133	0 - 1000		±0.07	1220	17.0

Inch Code No. Range (in) Graduation (in) Maximum permissible error EMPE (in)* Height (mm) Mass (kg) 4.2 192-150 0 - 12 ±0.0015 470 192-151 0 - 18 648 9.2 0.001 ±0.002 192-152 0 - 24 798 9.8 ±0.003 192-153 0 - 40 1220 17.0

* Maximum permissible error, EMPE is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

05-13

DIMENSIONS





Mitutoyo

Height Gage Optional Accessories for Height Gages

SPECIFICATIONS (Scriber)

Metric					
Code No.	Applicable Height Gages				
	192 Series Digimatic Height Gages (192-613-10, 192-614-10, 192-615-10)				
	570 Series Digimatic Height Gages (570-302, 570-304)				
07GZA000	192 Series Dial Height Gages (192-130, 192-131, 192-132, 192-133)				
	514 Series Vernier Height Gages (514-102, 514-104, 514-106, 514-103, 514-105, 514-107)				
	570 Series Digimatic Height Gages (570-402/404)				
900168	514 Series Vernier Height Gages (514-160/172)				
	192 Series Digimatic Height Gages (192-663-10, 192-664-10, 192-665-10)				
905200	570 Series Digimatic Height Gage (570-230)				
	514 Series Vernier Height Gages (514-108, 514-109)				
900390	514 Series Vernier Height Gage (514-170)				
Inch					
Code No.	Applicable Height Gages				
000172	570 Series Digimatic Height Gages (570-227, 570-244)				
900173	506 Series Vernier Height Gages (506-201/207/204, 506-208)				
	192 Series Digimatic Height Gages (192-630-10, 192-631-10, 192-632-10, 192-633-10)				
900258	570 Series Digimatic Height Gages (570-412, 570-413, 570-414)				
	574 Series Heightmatic (574-212-1, 574-211-1, 574-210-1)				
005201	192 Series Digimatic Height Gages (192-670-10, 192-671-10, 192-672-10, 192-673-10)				
903201	570 Series Digimatic Height Gage (570-248)				

DIMENSIONS (Scriber)

900173 905200 (150) (47) (45) 105 m 13 42 (32.5) 2.7 5.35 6 900390 07GZA000 900168 144 16 n πţ 16 32 50 \$ 50 0.5 14 22 0 ∞⊨⊡ 12 6 26 2 Values in parenthesis are reference dimensions.



Accessories, Options

Unit: mm



Height Gage Optional Accessories for Height Gages

Dial Test Indicators

• For information about the attachment of dial test indicators, refer to page 07-84.







• Allows quick measurement

• Mounting bar section: 9×9 mm

between holes.

1 to 38 mm

of center-to-center distance

951144

900872

- This is a convenient sensor to be attached to both the workpiece^{*1} and the height gage^{*2}, giving a lamp display when the scriber touches the workpiece. *1 Conductive workpieces only. *2 Attach to a conductive part. • Magnet is incorporated.
- Battery (PR44, 2 pcs. required) is not included.
- Use it on a precision black granite surface plate. (Refer to page 01-51)

Depth Gage Attachment



900764

- Attaches to a height gage for measuring groove and hole depth.
- Minimum hole diameter: 5.5 mm
- Measurable hole diameters:
 Maximum distance from the bottom of the holding bar to the contact point: 80 mm (metric type), 2.95 in (inch type)
 - Dial indicator contact points are usable. (Refer to pages 07-63 and 07-64.)
 - Mounting bar section: 9×9 mm
 - Holding bar length: 100 mm





Typical applications



Checking accuracy of caliper (outside measurement)



Checking accuracy of caliper (inside measurement)



Checking accuracy of height gage

Optional Accessories

- 602162: Wooden case for 300 mm, 12 inch model 602164: Wooden case for 600 mm model

CERA Caliper Checker SERIES 515

- Designed to inspect calipers.
- Can also stand perpendicular to a surface for height gage inspection.



5 Height Gages

SPECIFICATIONS

Metric	I					
Codo No	Range (mm)	Block pitch accuracy*		Parallelism of blocks*		Mass (kg)
Code No.		20 - 300 mm	350 - 600 mm	20 - 300 mm	350 - 600 mm	ividss (kg)
515-555	0 - 300	. E O um	—	20.00	_	4
515-556-2	0 - 600	±5.0 µm	±7.0 μm	2.0 µm	4.0 µm	8.5
Inch	I					
Codo No	Pango (in)	Block pitch	accuracy*	Parallelism	of blocks*	Mass (kg)
Coue No.	nange (iii)	1 - 12 in		1 - 12 in		IVIdSS (KY)
515-565	0 - 12	±0.0002 in		0.00008 in		4

The block accuracy and the parallelism of blocks are based on the following:
 Outside caliper and height gage: lower end reference plane
 Inside caliper: inside reference plane

DIMENSIONS



